

Backflow Assembly Test Report

Made By Mako Assist on: 09/11/2023 at 7:13 PM

SITE

Water Authority: CFPUA
Contact Name: Eric Bolin
Service Address: 8783 Ramsbury Way
Wilmington, NC 28411
United States

ASSEMBLY

Type: RP
Size: 1 INCH
Manufacturer: apollo/conbraco
Model: rp4a
Serial Number: 764807
Geo Tag: 34.3027285019013
-77.76738085267165



TEST GAUGE

Name: MAKO MK5
Serial Number: 2AC22040057
Calibration Date: 2023-01-16

TEST RESULTS

Test Procedure Followed: UF TREEO

Relief Valve Opening Point (RV) (PSID):	2.7	RV Fully Opened?:	YES
Check Valve 1 (CV 1) (PSID):	6.7	CV 1 Held Tight?:	YES
Line Pressure (LP) (PSID):	67.0	CV 2 Held Tight?:	YES
Check Valve 2 (CV 2) (PSID):	2.0	SOV 2 Closed Tight?:	YES

COMMENTS

APO #0012728
Assembly located on
left side of house

Buffer = 4.0 psi

PASS

CERTIFIED BY:

Eric Bolin

Name: Eric Bolin
Certificate #: RWCT2760
Company: EHS Management Solutions, LLC
Phone: 4044326736
Email: ebolin69@icloud.com